

# 附件表



022----81794882 81794859 85823692  
28314117 28327302 28327307



022----28314117 28327302 28327307



[lm866@126.com](mailto:lm866@126.com) [www.clamp668.com](http://www.clamp668.com)



13323362328

天津好手 06版

# 附件表

## ADJUSTABLE SPINDLE ASSEMBLIES 橡胶压头螺丝



FLAT CUSHION-TIP BOUNDED NEOPRENE CAP

Part No.	Description	Part No.	Description
压头螺丝代码	规格(公制)	压头螺丝代码	规格(英制)
FC-042507	M4x25 P=0.7	FC-10138	10-24x1 <sup>3</sup> / <sub>8</sub>
FC-044207	M4x42 P=0.7	FC-14134	1/4-20x1 <sup>3</sup> / <sub>4</sub>
FC-064410	M6x44 P=1.0	FC-14218	1/4-20x2 <sup>1</sup> / <sub>8</sub>
FC-065110	M6x51 P=1.0	FC-56212	5/16-18x2 <sup>1</sup> / <sub>2</sub>
FC-086312	M8x63 P=1.25	FC-56300	5/16-18x3
FC-087512	M8x75 P=1.25	FC-38312	3/8-16x3 <sup>1</sup> / <sub>2</sub>
FC-108515	M10x85 P=1.5	FC-38412	3/8-16x4 <sup>1</sup> / <sub>2</sub>
FC-121017	M12x100 P=1.75	FC-12334	1/2-13x3 <sup>3</sup> / <sub>4</sub>

## ADJUSTABLE SPINDLE ASSEMBLIES 外六角螺丝压头



STANDARD ADJUSTABLE

Part No.	Description	Part No.	Description
压头螺丝代码	规格(公制)	压头螺丝代码	规格(英制)
SA-041507	M4x15 P=0.7	SA-08034	8-32x <sup>3</sup> / <sub>4</sub> (nylon)
SA-042007	M4x20 P=0.7	SA-10118	10-24x1 <sup>1</sup> / <sub>8</sub>
SA-042507	M4x25 P=0.7	SA-14112	1/4-20x1 <sup>1</sup> / <sub>2</sub>
SA-043407	M4X34 P=0.7(NYLON)	SA-14134	1/4-20x1 <sup>3</sup> / <sub>4</sub>
SA-044007	M4x40 P=0.7	SA-56200	5/16-18x2
SA-051508	M5x15 P=0.8	SA-56212	5/16-18x2 <sup>1</sup> / <sub>2</sub>
SA-053008	M5x30 P=0.5	SA-38300	3/8-16x3
SA-064010	M6x40 P=1.0	SA-38400	3/8-16x4
SA-065101	M6x50 P=1.0	SA-12300	1/2-13x3
SA-083012	M8x30 P=1.25	SA-12412	1/2-13x4 <sup>1</sup> / <sub>2</sub>
SA-085012	M8x50 P=1.25	SA-58500	5/8-11x5

SA-086512	M8x65 P=1.25		
SA-105015	M10X50 P=1.5		
SA-106515	M10x65 P=1.5		
SA-107515	M10x75 P=1.5		
SA-109015	M10x90 P=1.5		
SA-185025	M18x50 P=2.5		

### ADJUSTABLE SPINDLE ASSEMBLIES 橡胶尖压头螺丝



CONE CUSHION-TIP BONDED NEOPRENE CAP

Part No. 压头螺丝代码	Description 规格(英制)
CC-10138	10-24x1 <sup>3</sup> / <sub>8</sub>
CC-14134	<sup>1</sup> / <sub>4</sub> -20x1 <sup>3</sup> / <sub>4</sub>
CC-14218	<sup>1</sup> / <sub>4</sub> -20x2 <sup>1</sup> / <sub>8</sub>
CC-56212	<sup>5</sup> / <sub>16</sub> -18x2 <sup>1</sup> / <sub>2</sub>
CC-38312	<sup>3</sup> / <sub>8</sub> -16x3 <sup>1</sup> / <sub>2</sub>

### SWIVEL FOOT ADJUSTABLE SPINDLE ASSEMBLIES 万向调节紫铜螺丝



Part No. 压头螺丝代码	Description 规格(公制)	Part No. 压头螺丝代码	Description 规格(英制)
SF-05035	M5X35 P=0.8	SF-14214	<sup>1</sup> / <sub>4</sub> -20x2 <sup>1</sup> / <sub>4</sub>
SF-06050	M6X50 P=1.0	SF-56234	<sup>5</sup> / <sub>16</sub> -18x2 <sup>3</sup> / <sub>4</sub>
SF-08065	M8X65 P=1.25	SF-38300	<sup>3</sup> / <sub>8</sub> -16x3
SF-10085	M10X85 P=1.5	SF-12400	<sup>1</sup> / <sub>2</sub> -13x4
-SF-12100	M12X100 P=1.75		
SF-16150	M16X150 P=2.0		

### FLANGED WASHERS FOR "U" BAR CLAMPS ONLY 压把螺丝专用垫片



Part No. 螺丝压把专用垫片代码	Description 规格(英制)
FW-080	For 8 Spindle
FW-100	For 10 Spindle
FW-140	For 1/4 Spindle
FW-141	For 1/4 Spindle
FW-516	For 5/16 Spindle
FW-380	For 3/8 Spindle
FW-120	For 1/2 Spindle
FW-580	For 5/8 Spindle

**NEOPRENE CAPS 外六角压头螺丝专用橡胶帽**



Part No. 专用橡胶帽代码	Description 规格(英制)
NC-140	For 1/4 Spindle
-NC-516	For 5/16 Spindle
NC-380	For 3/8 Spindle
NC-120	For 1/2 Spindle

**BOLT RETAINERS "定点压把"螺丝定位卡**



WELD ON FOR SOLID-ARM CLAMPS

Part No. "定点压把"螺丝定位卡代码	Description 规格(英制)
-BR-140	For 1/4 Spindle
BR-141	For 1/4 Spindle
BR-516	For 5/16 Spindle
BR-380	For 3/8 Spindle
BR-120	For 1/2 Spindle
BR-580	For 5/8 Spindle